# YOUR ONESURVEY HOME REPORT

#### **ADDRESS**

30A Cowgate
Dundee
DD1 2JH

#### PREPARED FOR

lain Harvey

#### **INSPECTION CARRIED OUT BY:**

#### **SELLING AGENT:**



HOME REPORT GENERATED BY:

**Chamber Practice** 



### **Document Index**

Document	Status	Prepared By	Prepared On
Single Survey	Final	Dundee - Allied Surveyors Scotland Ltd	12/08/2024
Mortgage Certificate	Final	Dundee - Allied Surveyors Scotland Ltd	12/08/2024
Property Questionnaire	Final	Mr. lain Harvey	
EPC	FileUploaded	Dundee - Allied Surveyors Scotland Ltd	08/08/2024

#### **Important Notice:**

This report has been prepared for the purposes and use of the person named on the report. In order to ensure that you have sight of a current and up to date copy of the Home Report it is **essential** that you log onto www.onesurvey.org (free of charge) to download a copy personalised in your own name. This enables both Onesurvey and the Surveyor to verify that you have indeed had sight of the appropriate copy of the Home Report prior to your purchasing decision. This personalised report can then be presented to your legal and financial advisers to aid in the completion of your transaction. **Failure to obtain a personalised copy may prevent the surveyor having any legal liability to you as they will be unable to determine that you have relied on this report prior to making an offer to purchase.** 

Neither the whole, nor any part of this report may be included in any published document, circular or statement, nor published in any way without the consent of Onesurvey Ltd. Only the appointed Chartered Surveyor can utilise the information contained herein for the purposes of providing a transcription report for mortgage/loan purposes.

PART 1

## SINGLE SURVEY

A report on the condition of the property, with categories being rated from 1 to 3.



## Single Survey

## Survey report on:

Surveyor Reference	EA2070
Customer	Mr. lain Harvey
Selling address	30A Cowgate
	Dundee
	DD1 2JH
Date of Inspection	08/08/2024
Prepared by	Blair Ferguson, MRICS
	Dundee - Allied Surveyors Scotland Ltd

#### SINGLE SURVEY TERMS AND CONDITIONS (WITH MVR)

#### **PART 1 - GENERAL**

#### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property. <sup>1</sup>

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

 $\overline{\Omega}$ 

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

#### 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

<sup>&</sup>lt;sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Codes of Conduct

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

#### 1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller:
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

#### 1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

#### 1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report. 2

#### 1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

#### 1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

#### 1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for

expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

#### 1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

#### 1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.
- the "Market Value" is The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property.
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and

<sup>2</sup> Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Rules of Conduct.

- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

#### **PART 2 - DESCRIPTION OF THE REPORT**

#### 2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

#### 2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.* 

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

#### 2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not

significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 2.3.1 <u>Category 3</u>: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2.3.2 <u>Category 2</u>: Repairs or replacement requiring future attention, but estimates are still advised.
- 2.3.3 Category 1: No immediate action or repair is needed.

**WARNING**: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

#### 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

#### 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

#### 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

#### 2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an

arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- \*There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- ➤ \*There are no particularly troublesome or unusual legal restrictions;
- \*There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property

#### 1. INFORMATION AND SCOPE OF INSPECTION

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the Surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the Surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the Surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities will not be inspected or reported on.

Description	The property under review comprises a first floor flat contained with a three and half storey converted building containing four with secure entry system.	
Accommodation	FIRST FLOOR	
	Entrance Vestibule, Hall, Open Plan Lounge/Kitchen, Master Bedroom with En-Suite Shower Room, Second Bedroom and Bathroom.	
Gross internal floor area (m2)	Approximately 80 sq. m.	
Neighbourhood and location	Cowgate is located within the city centre of Dundee and the subjects form part of a well established mixed residential/commercial development varying in property style ages/types. The property is located within a Conservation Area and educational/shopping/retail facilities, including close proximity to a mainline railway station, are available nearby.	
Age	The original building dates back to the late 19th century and the age of the conversion is circa 5 years old.	
Weather	It was dry and cloudy.	
Chimney stacks	The chimney heads are of stone/brick construction, and where seen, some have cement flashings.	
	Visually inspected with the aid of binoculars where required.	

Roofing including roof space  The roof is assumed to have a timber frame and is clad externally with slates.  Sloping roofs were visually inspected with the aid of binoculars where required.  Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.  Roofs are prone to water penetration during adverse weather but it is not always possible for surveyors to identify this likelihood in good or dry weather. All roofs should be inspected and repaired by reputable tradesmen on an annual basis and especially after storms.  Rainwater fittings  The rainwater goods are predominantly metal.  Visually inspected with the aid of binoculars where required.  Visually inspected with the aid of binoculars where required.  Foundations and concealed parts were not exposed or inspected.  Windows, external doors are replacement casement style timber/double glazed units and both entrance doors are good quality composite/timber installations. Internal and external doors were opened and closed where keys were available.  Doors and windows were opened and closed where keys were available.  Poors and windows were opened and closed where possible.  Doors and windows were not forced open.  External decorations  The aforementioned timbers have a paint finish.  Visually inspected.  Conservatories / porches  Not applicable.  Communal areas  There is a shared bin store, as well as a bike storage area.  Visually inspected.  Outside areas and boundaries  Not applicable.  The ceilings are plasterboard and there is also a hatch within the vestibule, allowing access to services.  Visually inspected from floor level.		
where required.  Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.  Roofs are prone to water penetration during adverse weather but it is not always possible for surveyors to identify this likelihood in good or dry weather. All roofs should be inspected and repaired by reputable tradesmen on an annual basis and especially after storms.  Rainwater fittings  The rainwater goods are predominantly metal.  Visually inspected with the aid of binoculars where required.  Visually inspected with the aid of binoculars where required.  Foundations and concealed parts were not exposed or inspected.  Windows, external doors and concealed parts were not exposed or inspected.  Windows, external doors and doth entrance doors are good quality composite/timber installations. Internal and external doors were opened and closed where keys were available.  Random windows were opened and closed where possible.  Doors and windows were not forced open.  External decorations  The aforementioned timbers have a paint finish.  Visually inspected.  Conservatories / porches  Not applicable.  Communal areas  There is a shared close/stair.  Circulation areas visually inspected.  Garages and permanent outbuildings  The cellings are plasterboard and there is also a hatch within the vestibule, allowing access to services.	, ,	<u> </u>
was safe and reasonable access, normally defined as being from a 3 mladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.  Roofs are prone to water penetration during adverse weather but it is not always possible for surveyors to identify this likelihood in good or dry weather. All roofs should be inspected and repaired by reputable tradesmen on an annual basis and especially after storms.  Rainwater fittings  The rainwater goods are predominantly metal.  Visually inspected with the aid of binoculars where required.  Main walls  The building is of substantial solid stone/brick construction with a facing stone finish.  Visually inspected with the aid of binoculars where required.  Foundations and concealed parts were not exposed or inspected.  The windows are replacement casement style timber/double glazed units and both entrance doors are good quality composite/timber installations.  Internal and external doors were opened and closed where keys were available.  Random windows were opened and closed where possible.  Doors and windows were opened and closed where possible.  Doors and windows were opened and closed where possible.  Doors and windows were not forced open.  External decorations  The aforementioned timbers have a paint finish.  Visually inspected.  Conservatories / porches  There is a shared close/stair.  Circulation areas visually inspected.  Garages and permanent outbuildings  There is a shared bin store, as well as a bike storage area.  Visually inspected.  Outside areas and boundaries  The ceilings are plasterboard and there is also a hatch within the vestibule, allowing access to services.		1
is not always possible for surveyors to identify this likelihood in good or dry weather. All roofs should be inspected and repaired by reputable tradesmen on an annual basis and especially after storms.  Rainwater fittings  The rainwater goods are predominantly metal.  Visually inspected with the aid of binoculars where required.  The building is of substantial solid stone/brick construction with a facing stone finish.  Visually inspected with the aid of binoculars where required.  Foundations and concealed parts were not exposed or inspected.  Windows, external doors and joinery  The windows are replacement casement style timber/double glazed units and both entrance doors are good quality composite/timber installations.  Internal and external doors were opened and closed where keys were available.  Random windows were opened and closed where possible.  Doors and windows were opened and closed where possible.  Doors and windows were not forced open.  External decorations  The aforementioned timbers have a paint finish.  Visually inspected.  Conservatories / porches  Not applicable.  Circulation areas visually inspected.  Garages and permanent outbuildings  There is a shared bin store, as well as a bike storage area.  Visually inspected.  Outside areas and boundaries  The ceilings are plasterboard and there is also a hatch within the vestibule, allowing access to services.		was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the
Main walls  The building is of substantial solid stone/brick construction with a facing stone finish.  Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected.  Windows, external doors and joinery  The windows are replacement casement style timber/double glazed units and both entrance doors are good quality composite/timber installations.  Internal and external doors were opened and closed where keys were available.  Random windows were opened and closed where possible.  Doors and windows were not forced open.  External decorations  The aforementioned timbers have a paint finish.  Visually inspected.  Conservatories / porches  Not applicable.  Circulation areas visually inspected.  Garages and permanent outbuildings  There is a shared bin store, as well as a bike storage area.  Visually inspected.  Outside areas and boundaries  The ceilings are plasterboard and there is also a hatch within the vestibule, allowing access to services.		is not always possible for surveyors to identify this likelihood in good or dry weather. All roofs should be inspected and repaired by
Main walls  The building is of substantial solid stone/brick construction with a facing stone finish.  Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected.  Windows, external doors and vindows are replacement casement style timber/double glazed units and both entrance doors are good quality composite/timber installations.  Internal and external doors were opened and closed where keys were available.  Random windows were opened and closed where possible.  Doors and windows were not forced open.  External decorations  The aforementioned timbers have a paint finish.  Visually inspected.  Conservatories / porches  Not applicable.  Circulation areas visually inspected.  Garages and permanent outbuildings  There is a shared close/stair.  Circulation areas visually inspected.  Outside areas and boundaries  Not applicable.  Ceillings  The ceilings are plasterboard and there is also a hatch within the vestibule, allowing access to services.	Rainwater fittings	The rainwater goods are predominantly metal.
stone finish.  Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected.  Windows, external doors and both entrance doors are good quality composite/timber installations.  Internal and external doors were opened and closed where keys were available.  Random windows were opened and closed where possible.  Doors and windows were not forced open.  External decorations  The aforementioned timbers have a paint finish.  Visually inspected.  Conservatories / porches  Not applicable.  Communal areas  There is a shared close/stair.  Circulation areas visually inspected.  Garages and permanent outbuildings  There is a shared bin store, as well as a bike storage area.  Visually inspected.  Outside areas and boundaries  The ceilings are plasterboard and there is also a hatch within the vestibule, allowing access to services.		Visually inspected with the aid of binoculars where required.
Windows, external doors and joinery  The windows are replacement casement style timber/double glazed units and joinery  Internal and external doors were opened and closed where keys were available.  Random windows were opened and closed where keys were available.  Doors and windows were opened and closed where possible.  Doors and windows were not forced open.  External decorations  The aforementioned timbers have a paint finish.  Visually inspected.  Conservatories / porches  Not applicable.  Circulation areas visually inspected.  Garages and permanent outbuildings  There is a shared close/stair.  Circulation areas visually inspected.  Outside areas and boundaries  The ceilings are plasterboard and there is also a hatch within the vestibule, allowing access to services.	Main walls	
and joinery  and both entrance doors are good quality composite/timber installations.  Internal and external doors were opened and closed where keys were available.  Random windows were opened and closed where possible.  Doors and windows were not forced open.  External decorations  The aforementioned timbers have a paint finish.  Visually inspected.  Conservatories / porches  Not applicable.  Circulation areas visually inspected.  Garages and permanent outbuildings  There is a shared close/stair.  Circulation areas visually inspected.  Outside areas and boundaries  Not applicable.  Not applicable.  Ceilings  The ceilings are plasterboard and there is also a hatch within the vestibule, allowing access to services.		
were available. Random windows were opened and closed where possible. Doors and windows were not forced open.  External decorations The aforementioned timbers have a paint finish. Visually inspected.  Conservatories / porches Not applicable.  Communal areas There is a shared close/stair. Circulation areas visually inspected.  Garages and permanent outbuildings There is a shared bin store, as well as a bike storage area. Visually inspected.  Outside areas and boundaries  The ceilings are plasterboard and there is also a hatch within the vestibule, allowing access to services.		· · · · · · · · · · · · · · · · · · ·
Doors and windows were not forced open.  External decorations  The aforementioned timbers have a paint finish.  Visually inspected.  Conservatories / porches  Not applicable.  Communal areas  There is a shared close/stair.  Circulation areas visually inspected.  Garages and permanent outbuildings  There is a shared bin store, as well as a bike storage area.  Visually inspected.  Outside areas and boundaries  Not applicable.  Ceilings  The ceilings are plasterboard and there is also a hatch within the vestibule, allowing access to services.		· · · · · · · · · · · · · · · · · · ·
External decorations  The aforementioned timbers have a paint finish.  Visually inspected.  Conservatories / porches  Not applicable.  There is a shared close/stair.  Circulation areas visually inspected.  Garages and permanent outbuildings  There is a shared bin store, as well as a bike storage area.  Visually inspected.  Outside areas and boundaries  Not applicable.  Ceilings  The ceilings are plasterboard and there is also a hatch within the vestibule, allowing access to services.		Random windows were opened and closed where possible.
Visually inspected.  Conservatories / porches  Not applicable.  Communal areas  There is a shared close/stair.  Circulation areas visually inspected.  Garages and permanent outbuildings  There is a shared bin store, as well as a bike storage area.  Visually inspected.  Outside areas and boundaries  Not applicable.  Ceilings  The ceilings are plasterboard and there is also a hatch within the vestibule, allowing access to services.		Doors and windows were not forced open.
Conservatories / porches  Not applicable.  There is a shared close/stair.  Circulation areas visually inspected.  Garages and permanent outbuildings  There is a shared bin store, as well as a bike storage area.  Visually inspected.  Outside areas and boundaries  Not applicable.  Ceilings  The ceilings are plasterboard and there is also a hatch within the vestibule, allowing access to services.	External decorations	The aforementioned timbers have a paint finish.
Communal areas  There is a shared close/stair.  Circulation areas visually inspected.  Garages and permanent outbuildings  There is a shared bin store, as well as a bike storage area.  Visually inspected.  Outside areas and boundaries  Not applicable.  Ceilings  The ceilings are plasterboard and there is also a hatch within the vestibule, allowing access to services.		Visually inspected.
Circulation areas visually inspected.  Garages and permanent outbuildings  There is a shared bin store, as well as a bike storage area.  Visually inspected.  Outside areas and boundaries  Not applicable.  Ceilings  The ceilings are plasterboard and there is also a hatch within the vestibule, allowing access to services.	Conservatories / porches	Not applicable.
Garages and permanent outbuildings  There is a shared bin store, as well as a bike storage area.  Visually inspected.  Outside areas and boundaries  Not applicable.  Ceilings  The ceilings are plasterboard and there is also a hatch within the vestibule, allowing access to services.	Communal areas	There is a shared close/stair.
Outside areas and boundaries  Not applicable.  Ceilings  The ceilings are plasterboard and there is also a hatch within the vestibule, allowing access to services.		Circulation areas visually inspected.
Ceilings  The ceilings are plasterboard and there is also a hatch within the vestibule, allowing access to services.		
vestibule, allowing access to services.		Not applicable.
Visually inspected from floor level.	Ceilings	1
		Visually inspected from floor level.

Internal walls	The internal walls have been plasterboard lined and some areas are tiled.  Visually inspected from floor level.  Using a moisture meter, walls were randomly tested for dampness
	where considered appropriate.
Floors including sub floors	The flooring is of suspended timber joist construction.
	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.
	Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.
Internal joinery and kitchen fittings	The kitchen has a stainless steel sink; fitted floor/wall mounted units; gas hob and integrated (NEFF) appliances. Internal doors/skirtings/facings are timber.
	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
Chimney breasts and fireplaces	Not applicable.
Internal decorations	Decorated areas include walls and ceilings.
	Visually inspected.
Cellars	Not applicable.
Electricity	The property has a mains electricity supply and the circuit board consumer unit; uPVC cabling and meter, can be found within the vestibule.
	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances.
	Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on.

Gas	There is a mains gas supply with internal meter.
	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances.
	Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on.
Water, plumbing and bathroom fittings	There is a mains cold water supply with modern white sanitary ware throughout, incorporating electric/mixer showers.
	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	Concealed areas around baths and shower trays cannot be inspected however water spillage over a period of time can result in unexpected defects to hidden parts of the building fabric.
Heating and hot water	Heating is sourced from a Worcester Greenstar 32CDi compact gas combination boiler, which can be found within the master bedroom cupboard. This provides central heating and domestic hot water to the property.
	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
Drainage	Drainage is understood to be to the Local Authority sewer.
	Drainage covers etc were not lifted.
	Neither drains nor drainage systems were tested.

## Fire, smoke and burglar alarms

There are smoke/heat detectors within the property.

Visually inspected.

No test whatsoever were carried out to any systems or appliances.

There is now a requirement in place for compliant interlinked fire, smoke and heat detectors in residential properties. The new fire smoke and alarm standard came into force in Scotland in February 2022, requiring a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat alarm also requires to be installed in each kitchen. The alarms need to be ceiling mounted and interlinked. Where there is a carbon fuelled appliance such as a boiler, open fire or wood burner etc. a carbon monoxide detector is also required.

The surveyor will only comment on the presence of a smoke detector etc. but will not test them, ascertain if they are in working order, interlinked and / or fully compliant with the fire and smoke alarm standard that was introduced in 2022.

We have for the purposes of the report, assumed the system is fully compliant, if not then the appropriate compliant system will required to be installed prior to sale. This of course should be confirmed by your legal advisor.

## Any additional limits to inspection

The floor surfaces were hidden by fitted floor coverings. No sub-floor inspection could be carried out.

No proper sight of the roof coverings to the front could be obtained and our inspection of the chimney heads, was limited from ground level. In addition, scaffolding was erected during the inspection which hindered our inspection somewhat.

Only the subject flat and internal communal areas giving access to the flat were inspected.

If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the Surveyor will assume that there are no defects that will have a material effect on the valuation.

The building containing the flat, including any external communal areas, was visually inspected only to the extent that the Surveyor is able to give an opinion on the general condition and standard of maintenance.

An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor. If it exists removal must be undertaken in a controlled manner by specialist contractors. This can prove to be expensive.

Normal maintenance is not treated as a repair for the purposes of the Single Survey. When a category 1 rating is provided this means the property must continue to be maintained in the normal way.

#### Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

#### 2. CONDITION

This section identifies problems and tells you about the urgency of any repairs by using one of the above 3 categories:

Category 3	Category 2	Category 1
to other parts of the property or cause a safety	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movemen	t
Repair category:	
Notes:	There was no evidence to suggest any recent movement has taken place.

Dampness, rot and infestation		
Repair category:		
Notes:	There is a damp stain above the larger front bedroom window and this area could not be tested. We have been advised that this is an old damp stain and repairs, externally, have rectified this.	

Chimney stacks		
Repair category:		
Notes:	From our limited inspection, no signficant defects were apparent. Normal (shared) works of repair and maintenance, should continue to be carried out.	

Roofing including roof space		
Repair category:	2	
Notes:	No proper sight of the slater work could be obtained, however, our valuation assumes that this is of an older type.	
	Taking the age and type of roof coverings into consideration, future (shared) works of repair and maintenance, should continue to be carried out.	

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Rainwater fittings	
Repair category:	
Notes:	No major defects were noted.

Main walls	
Repair category:	
Notes:	There is deterioration/weathering to the sill within the lounge/kitchen area and areas have been repointed in the past.

Windows, external doors and joinery	
Repair category:	1
Notes:	No significant defects were identified.
	Double glazed/replacement windows and doors can become problematic and over time the operation of same can be affected with opening mechanisms becoming damaged. It is therefore, likely that maintenance repairs maybe required as part and parcel of an ongoing maintenance programme.

External decorations	
Repair category:	
Notes:	No significant defects were noted.

Conservatories / porches	
Repair category:	
Notes:	Not applicable.

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Communal areas	
Repair category:	2
Notes:	Overall, the close/stair is well maintained. With that said, there is evidence of dampness near the shared close door, as well as within the bin store.

Garages and permanent outbuildings	
Repair category:	
Notes:	Not applicable.

Outside areas and boundaries	
Repair category:	
Notes:	No significant defects were identified.

Ceilings	
Repair category:	1
Notes:	As stated earlier, there is a damp stain within the larger (second) bedroom.

Internal walls	
Repair category:	
Notes:	Shrinkage cracking noted through plasterwork.

Floors including sub-floors	
Repair category:	
Notes:	Within the limits of the inspection, no major defects were noted.

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Internal joinery and kitchen fittings	
Repair category:	1
Notes:	The door handle into the second bedroom is loose and no major defects were identified.

Chimney breasts and fireplaces	
Repair category:	
Notes:	Not applicable.

Internal decorations	
Repair category:	
Notes:	Some wear and tear noted.

Cellars	
Repair category:	
Notes:	Not applicable.

Electricity	
Repair category:	
Notes:	No significant defects were identified.
	The NIC/EIC recommend re-testing of the electrical supply every five years, or upon change of occupancy. Test certification, therefore, should be obtained.

Gas	
Repair category:	
Notes:	No significant defects were noted.

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Water, plumbing and bathroom fittings	
Repair category:	
Notes:	No significant defects were identified.

Heating and hot water	
Repair category:	
Notes:	Our valuation assumes that the boiler has been serviced in the past. Any documentation and/or service history should be transferred to the incoming purchaser.

Drainage	
Repair category:	
Notes:	Within the limits of the inspection, no major defects were noted.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the comments above for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	1
Roofing including roof space	2
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	1
Conservatories / porches	
Communal areas	2
Garages and permanent outbuildings	
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	
Internal decorations	1
Cellars	
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

#### Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

#### Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

#### 3. ACCESSIBILITY INFORMATION

**Guidance Notes on Accessibility Information** 

<u>Three steps or fewer to a main entrance door of the property:</u> In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

<u>Unrestricted parking within 25 metres:</u> For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coinoperated machines.

1. Which floor(s) is the living accommodation on?	First Floor.
2. Are there three steps or fewer to a main entrance door of the property?	[ ]YES [x]NO
3. Is there a lift to the main entrance door of the property?	[ ]YES [x]NO
4. Are all door openings greater than 750mm?	[x]YES [ ]NO
5. Is there a toilet on the same level as the living room and kitchen?	[x]YES [ ]NO
6. Is there a toilet on the same level as a bedroom?	[x]YES [ ]NO
7. Are all rooms on the same level with no internal steps or stairs?	[x]YES [ ]NO
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	[ ]YES [x]NO

#### 4. VALUATION AND CONVEYANCER ISSUES

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated re-instatement cost for insurance purposes.

#### Matters for a solicitor or licensed conveyancer

All rights of way, boundaries and maintenance liabilities should be verified for the property.

The property has been professionally converted and our valuation assumes that full Local Authority consents, will have been obtained.

Our valuation assumes that there is a Factor/Management Company responsible for the close/stair.

Scaffolding was erected during the inspection and full details of any repairs should be highlighted.

The property is located within Central Conversation Area.

Where items of maintenance or repair have been identified, the purchaser should satisfy themselves as to the costs and implications of these issues prior to making an offer to purchase.

#### Estimated re-instatement cost (£) for insurance purposes

330,000

Three Hundred and Thirty Thousand Pounds.

#### Valuation (£) and market comments

200.000

Two Hundred Thousand Pounds.

Our valuation reflects current market conditions relating to this area. We would assume that current trends will prevail at the ultimate date of disposal with no adverse or onerous matters being introduced into the market during the intervening period which would have a detrimental effect on price.

Report author:	Blair Ferguson, MRICS		
Company name:	Dundee - Allied Surveyors Scotland Ltd		
Address:	8 Whitehall Crescent Dundee DD1 4AU		
Signed:	Electronically Signed: 265845-caea763d-f70b		
Date of report:	12/08/2024		

# MORTGAGE VALUATION **REPORT**

Includes a market valuation of the property.





	Mortgage Valuation Report						
Property:	30A Cowgate Dundee DD1 2JH	Client: Mr. Iai	in Harvey olute Ownership				
Date of Inspection:	08/08/2024	Reference:	BF/LN/EA2070				

This report has been prepared as part of the seller's instructions to carry out a Single Survey on the property referred to above. The purpose of this report is to summarise the Single Survey for the purpose of advising a potential lender on the suitability of the property for mortgage purposes. The decision as to whether mortgage finance will be provided is entirely a matter for the lender. You should not rely on this report in making your decision to purchase but consider all the documents provided in the Home Report. Your attention is drawn to the additional comments elsewhere within the report which set out the extent and limitations of the service provided. This report should be read in conjunction with the Single Survey Terms and Conditions (with MVR). In accordance with RICS Valuation – Global Standards 2017 this report is for the use of the party to whom it is addressed or their named client or their nominated lender. No responsibility is accepted to any third party for the whole or any part of the reports contents. Neither the whole or any part of this report may be included in any document, circular or statement without prior approval in writing from the surveyor.

#### 1.0 LOCATION

Cowgate is located within the city centre of Dundee and the subjects form part of a well established mixed residential/commercial development varying in property style ages/types. The property is located within a Conservation Area and educational/shopping/retail facilities, including close proximity to a mainline railway station, are available nearby.

2.0	DESCRIPTION	2.1 Age:	The original building dates	
			back to the late 19th	
			century and the age of the	
			conversion is circa 5 years	
			old.	

The property under review comprises a first floor flat contained with a three and half storey converted building containing four with secure entry system.

#### 3.0 CONSTRUCTION

Stone/brick walls with pitched/slate roofs.

#### 4.0 ACCOMMODATION

#### FIRST FLOOR

Entrance Vestibule, Hall, Open Plan Lounge/Kitchen, Master Bedroom with En-Suite Shower Room, Second Bedroom and Bathroom.

5.0	SERVICES (	SERVICES (No tests have been applied to any of the services)					
Water:	Mains	Electricity:	Electricity: Mains Gas: Mains Drainage: Mains				
Central Heating:		Gas fired boiler.					
6.0	OUTBUILDIN	OUTBUILDINGS					
Garage: None.							
Others:		Shared bin/bike stores.					

7.0	GENERAL CONDITION - A building survey has not been carried out, nor has any inspection been made of any woodwork, services or other parts of the property which were covered, unexposed or inaccessible. The report cannot therefore confirm that such parts of the property are free from defect. Failure to rectify defects, particularly involving water penetration may result in further and more serious defects arising. Where defects exist and where remedial work is necessary, prospective purchasers are advised to seek accurate estimates and costings from appropriate Contractors or Specialists before proceeding with the purchase. Generally we will not test or report on boundary walls, fences, outbuildings, radon gas or site contamination.							
	presented/appointed property pe of construction.	y which has be	en kept in a structural conditi	on which is cor	nsistent with			
8.0	ESSENTIAL REPAIR WOR property)	<b>K</b> (as a condit	ion of any mortgage or, to pre	serve the cond	dition of the			
None.								
8.1 Retention	recommended:	-						
9.0	ROADS & FOOTPATHS							
Made.								
10.0	BUILDINGS INSURANCE (£):	330,000	GROSS EXTERNAL FLOOR AREA	94	Square metres			
	the property in its existing de No allowance has been inclu	esign and mate uded for inflatio	on a re-instatement basis as erials. Furnishings and fittings on during the insurance period other than on professional fe	s have not beer d or during re-d	n included. construction			
11.0	GENERAL REMARKS							
		nce liabilities s	should be verified for the prop	ertv.				
	has been professionally conv		valuation assumes that full Lo	•	consents, will			
Our valuation	assumes that there is a Fact	or/Manageme	nt Company responsible for th	ne close/stair.				
Scaffolding w	as erected during the inspect	ion and full de	tails of any repairs should be	highlighted.				
The property	The property is located within Central Conversation Area.							
Where items of maintenance or repair have been identified, the purchaser should satisfy themselves as to the costs and implications of these issues prior to making an offer to purchase.								
12.0								

	all necessary Local Authorit obtained. No investigation of we consider such matters to 2000 may contain asbestos without a test. It is beyond to	s, onerous burdens, title restrictions or servitude rights. It is assumed that ty consents, which may have been required, have been sought and of any contamination on, under or within the property has been made as to be outwith the scope of this report. All property built prior to the year in one or more of its components or fittings. It is impossible to identify the scope of this inspection to test for asbestos and future occupants bey have any concerns then they should ask for a specialist to undertake					
12.1	Market Value in present condition (£):	200,000	Two Hundred Thousand Pounds.				
12.2	Market Value on completion of essential works (£):						
12.3	Suitable security for normal mortgage purposes?	Yes					
12.4	Date of Valuation:	08/08/2024					

Signature: Electronically		Signed: 2658	45-caea763d-f70b			
Surveyor:	Blair Ferguso	n	MRICS		Date:	12/08/2024
Dundee - Allied Surveyors Scotland Ltd						
Office:	ce: 8 Whitehall Crescent Dundee DD1 4AU		Tel: 01382 349 930 Fax: email: dundee@alliedsurveyorsscotland.com			

PART 3

# ENERGY REPORT

A report on the energy efficiency of the property.



## energy report

## energy report on:

Property address	30A Cowgate  Dundee  DD1 2JH
Customer	Mr. lain Harvey
Customer address	30A Cowgate
	Dundee
	DD1 2JH
Prepared by	Blair Ferguson, MRICS
	Dundee - Allied Surveyors Scotland Ltd

### **Energy Performance Certificate (EPC)**

**Dwellings** 

## **Scotland**

#### 30A COWGATE, DUNDEE, DD1 2JH

Dwelling type:Mid-floor flatDate of assessment:08 August 2024Date of certificate:08 August 2024

Total floor area: 80 m<sup>2</sup>

Primary Energy Indicator: 80 kWh/m²/year

**Reference number:** 4014-9928-2530-2158-0202 **Type of assessment:** RdSAP, existing dwelling

Approved Organisation: Elmhurst

**Main heating and fuel:** Boiler and radiators, mains

gas


#### You can use this document to:

Compare current ratings of properties to see which are more energy efficient and environmentally friendly

#### Estimated energy costs for your home for 3 years\*

£1,656

 $^st$  based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




#### **Energy Efficiency Rating**

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band B (85)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



#### **Environmental Impact (CO<sub>2</sub>) Rating**

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO<sub>2</sub>) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band B (89)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

#### Top actions you can take to save money and make your home more efficient

There are currently no improvement measures recommended for your home.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

#### Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Sandstone or limestone, as built, insulated (assumed)	****	****
Roof	(another dwelling above)	_	_
Floor	(another dwelling below)	_	_
Windows	Fully double glazed	****	****
Main heating	Boiler and radiators, mains gas	****	<b>★★★★</b> ☆
Main heating controls	Programmer, room thermostat and TRVs	****	****
Secondary heating	None	_	_
Hot water	From main system	****	****
Lighting	Low energy lighting in 96% of fixed outlets	****	****

#### The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.

#### The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 14 kg CO<sub>2</sub>/m<sup>2</sup>/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 1.1 tonnes of carbon dioxide every year. You could reduce emissions by switching to renewable energy sources.

#### Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£855 over 3 years	£855 over 3 years	
Hot water	£459 over 3 years	£459 over 3 years	N. ( P. 11
Lighting	£342 over 3 years	£342 over 3 years	Not applicable
Totals	£1,656	£1,656	

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

#### **Recommendations for improvement**

None

#### Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

#### Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	1,601	N/A	N/A	N/A
Water heating (kWh per year)	1,832			

#### **About this document**

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Blair Ferguson Assessor membership number: EES/019846

Company name/trading name: Allied Surveyors Scotland Ltd

Address: 8 Whitehall Crescent

Dundee DD1 4AU 01382 349930

Phone number: 01382 349930 gary.black@alliedsurveyorsscotland.com

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

#### Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

## PROPERTY QUESTIONNAIRE

The owner of the property is required to complete this document which asks for information on the property such as 'Which council tax band?' etc.



Property Address	30A Cowgate
	Dundee
	DD1 2JH
Seller(s)	lain Harvey
Completion date of property questionnaire	
Note for sellers	

1.	Length of ownership	
	How long have you owned the property?	
	6 years 4 months	
2.	Council tax	
	Which Council Tax band is your property in? (Please circle)	
	[ ]A [ ]B [x]C [ ]D [ ]E [ ]F [ ]G [ ]H	
3.	Parking	
	What are the arrangements for parking at your property?	
	(Please tick all that apply)	
	Garage	[]
	Allocated parking space	[]
	Driveway	[]
	Shared parking	[]
	On street	[]
	Resident permit	[]
	Metered parking	[]
	Other (please specify):	No Parking

4.	Conservation area	
	Is your property in a designated Conservation Area (that is an area of	[]YES[]NO
	special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?	[x]Don't know
5.	Listed buildings	_
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	[x]YES [ ]NO
6.	Alterations/additions/extensions	
a	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	[ ]YES [x]NO
	If you have answered yes, please describe below the changes which you have made:	
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	[]YES[]NO
	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.	
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:	
Ь	Have you had replacement windows, doors, patio doors or double glazing installed in your property	[ ]YES [x]NO
	If you have answered yes, please answer the three questions below:	
	(i) Were the replacements the same shape and type as the ones you replaced?	[]YES[]NO
	(ii) Did this work involve any changes to the window or door openings?	[]YES[]NO
	(iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):	
	Please give any guarantees which you received for this work to your solicitor or estate agent.	
7.	Central heating	
а	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of	[x]YES [ ]NO
	the property - the main living room, the bedroom(s), the hall and the bathroom).	[ ]Partial

	If you have answered yes or partial - what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).	
	Gas	
	If you have answered yes, please answer the three questions below:	
	(i) When was your central heating system or partial central heating system installed?	
	2018	
	(ii) Do you have a maintenance contract for the central heating system?	[ ]YES [x]NO
	If you have answered yes, please give details of the company with which you have a maintenance contract	
	(iii) When was your maintenance agreement last renewed? (Please provide the month and year).	
8.	Energy Performance Certificate	
	Does your property have an Energy Performance Certificate which is less than 10 years old?	[x]YES [ ]NO
9.	Issues that may have affected your property	
а	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	[ ]YES [x]NO
	If you have answered yes, is the damage the subject of any outstanding insurance claim?	[]YES[]NO
b	Are you aware of the existence of asbestos in your property?	[ ]YES [x]NO
	Are you aware or the existence of aspestos in your property!	[]Don't know
	If you have answered yes, please give details:	
10.	Services	

	Services	Connected	Supplier	
	Gas or liquid petroleum gas	Υ	Not known Pi	roperty rented
	Water mains or private water supply	Y	Not known Pi	roperty rented
	Electricity	Υ	Not known P	roperty rented
	Mains drainage	Υ	Not known P	roperty rented
	Telephone	N		
	Cable TV or satellite	N		
	Broadband	Υ	Not known P	roperty rented
)	Is there a septic tank system at your prop	erty?		[ ]YES [x]NO
	If you have answered yes, please answer	r the two questio	ns below:	
	(i) Do you have appropriate consents for the discharge from your septic		[]YES[]NO	
	tank?			[]Don't know
	(ii) Do you have a maintenance contract t	for your septic ta	nk?	[]YES[]NO
	If you have answered yes, please give de which you have a maintenance contract:	etails of the comp	oany with	
11.	Responsibilities for shared or common areas			
a	Are you aware of any responsibility to cou used jointly, such as the repair of a share boundary, or garden area?			[x]YES [ ]NO
	If you have answered yes, please give de	etails:		[]Don't know
	Common areas and building			
)	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?		[x]YES [ ]NO	
	If you have answered yes, please give de	etails:		[ ]N/A
	Building fabric and roof. Taken care of by	factor		
С	Has there been any major repair or replace during the time you have owned the prop		art of the roof	[x]YES [ ]NO
t	Do you have the right to walk over any of your neighbours' property- for example to put out your rubbish bin or to maintain your boundaries?		[ ]YES [x]NO	
	If you have answered yes, please give de	etails:		

е	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?	[ ]YES [x]NO
	If you have answered yes, please give details:	
f	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privatelyowned.)	[ ]YES [x]NO
	If you have answered yes, please give details:	
12.	Charges associated with your property	
а	Is there a factor or property manager for your property? If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:	[x]YES [ ]NO
	Taylor and Martin Property Management, 58 Bell St, Dundee DD1 1HF	
b	Is there a common buildings incurance policy?	[x]YES [ ]NO
	Is there a common buildings insurance policy?	[]Don't know
	If you have answered yes, is the cost of the insurance included in your	[x]YES [ ]NO
	monthly/annual factors charges?	[]Don't know
С	Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.	
	Taylor and Martin Property Management, 58 Bell St, Dundee DD1 1HF	
13.	Specialist works	
а	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	[x]YES [ ]NO
	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.	
	Renovation work to repair roof, guttering and fabric of building just finishing, Partly financed by Dundee council and project Mange by Loria Consulting and Taylor and Martin	
b	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?	[x]YES [ ]NO
	If you have answered yes, please give details:	
	See above	
С	If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?	[]YES[]NO

If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate. Guarantees are held by:

14.	Guarantees	
а	Are there any guarantees or warranties for any of the following:	
(i)	Electrical work	[ ]NO [ ]YES [x]Don't know [ ]With title deeds [ ]Lost
(ii)	Roofing	[ ]NO [ ]YES [x]Don't know [ ]With title deeds [ ]Lost
(iii)	Central heating	[ ]NO [ ]YES [x]Don't know [ ]With title deeds [ ]Lost
(iv)	National House Building Council(NHBC)	[ ]NO [ ]YES [x]Don't know [ ]With title deeds [ ]Lost
(v)	Damp course	[ ]NO [ ]YES [x]Don't know [ ]With title deeds [ ]Lost
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	[]NO[]YES[x]Don't know[]With title deeds[]Lost
b	If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):	
С	Are there any outstanding claims under any of the guarantees listed above?	[ ]YES [x]NO
	If you have answered yes, please give details:	

15.	Boundaries	
	So far as you are aware, has any boundary of your property been	[]YES[]NO
	moved in the last 10 years?	[x]Don't know
	If you have answered yes, please give details:	
16.	Notices that affect your property	
In the past three years have you ever received a notice:		
а	advising that the owner of a neighbouring property has made a planning application?	[ ]YES [x]NO
b	that affects your property in some other way?	[ ]YES [x]NO
С	that requires you to do any maintenance, repairs or improvements to your property?	[ ]YES [x]NO
	If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property.	

Declaration by the seller(s)/or other authorised body or person(s) I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.	
Signature(s):	lain and Rofiah Harvey
Capacity:	[x]Owner
Оараску.	[ ]Legally Appointed Agent for Owner
Date:	06/08/2024